
AOA ALERT

Effective Tuesday September 2 at 0600 Hours to Wednesday September 24, 2025



Post 2 Access Restrictions

Post 2 will be restricted for approximately 20 days to allow for repairs and replacement of the security gate.

During this period, all vehicles **MUST** enter the airfield through Post 2A.

Exception: Due to their size, supertugs will be permitted to continue using Post 2 for entry, as they are too large to pass through Post 2A. All other airport vehicles are required to use Post 2A for airfield access.

While repairs are underway, Post 2 will remain available as an **EXIT ONLY**.







